



The tolerances for connector positions in back plate of enclosure and tray should are not being taking into account.

We only considered the tolerances of max. movement (space) enclosure in tray.